

Sensor - CO, CO2, Gas, Humidity, Weather Station

Type	Part Number	Description
GAS	JCA-CO2-D2	CO2 Sensor, Duct Mount, 0-2000ppm/0-10VDC, 24vAC
	JCA-CO2-W	CO2 Sensor, Wall Mount, 0-2000ppm/0-10VDC, 24vAC (100x80)
	JCA-CO2-WT1	CO2 Sensor, Wall Mount, 0-2000ppm/0-10VDC, with NTC 10 K temp. sensor
	JCA-CO2-WT2	CO2 Sensor, Wall Mount, 0-2000ppm/0-10VDC, with PT1000 temp. sensor
	CD-W00-00-2	CO2 Sensor, Wall Mount, 0-2000ppm/0-10VDC, 24vAC (127x81)
	CD-P00-00-0	CO2 Sensor, Duct Mount, 0-2000ppm/0-10VDC, 24vAC
	CD-310-U00-00	CO2+RH+Temp sensor, 0-10vDC
	CD-311-U00-00	CO2+RH+Temp sensor, 0-10vDC, display
	JCA-CO-65-6525	CO Sensor, 0-100ppm/4-20mA, 2 wires loop power, Packed in Qty 5/box
	JCA-CO-V	CO Sensor, 0-100ppm/0-10vDC, 3 wires, In-built modbus RTU
	JCA-CO-D	CO Controller, 2 Relay ,0-10vDC & 4-20mA output, W/Display
	JCA-VOC	Indoor quality sensor, VOC
	JCA-NO2	NO2 Sensor, 0-10ppm/4-20mA, 24
	JCA-O2	O2 Sensor, 0-10ppm/4-20mA 24 v
	Refrigerant	JCA-REF-SS-1
JCA-REF-SS-2		Refrigerant controller, 2 relays, 24vAC (Nominated refrigerant when order)
JCA-TR5200		Combustible sensor, 4-20mA, 24vDC, 3 wires
Humidity	JCA-HT-9007-UD1	Humidity +temperature, Duct, 3%, NTC10K
	JCA-HT-9007-URB	Humidity +temperature, Wall, 3%, NTC10K
	JCA-HT-9007-OD	Humidity +temperature, Outdoor, 3%, NTC10K
	HT-1300-UR	Humidity sensor 4%, wall,
	HT-1301-UR	Humidity +temperature, wall, 4%, 0-10vDC/0-40C (80x80)
	HT-1201-UR	Humidity +temperature, wall, 2%, 0-10vDC/0-40C
	HT-1301-UD1	Humidity +temperature, duct, 2.5%, -15 to 60 /0-10vDC,
Weather Station	JCA-6420	Rain & Leaf wetness sensor, on/off
	JCA-7852	Rain collector, 0.2mm/pulse
	JCA-7911	Anemometer Wind speed direction sensor
	JCA-KTB-250	Anemometer interface card, 24vAC power
	JCA-LUX	Lux sensor, 0-10vDC, 24vAC, IP65, Range:0-1/2/4/8/20K
	JCA-HT-9007-OD	Humidity sensor 3%, outdoor, w/NTC10K temp sensor
	HE-68P3-0N000	IP65, Outdoor Temp+humidity, 0-10vDC, 24vAC
	JCA-RHP-3R2A	Outside Air Humidity Temp Sensor, Radiation Shield, Humidity 3% 0- 10V, Temp - 10 kOhm Type III
	TE-6363P-1	O/A sensor, 10KNTC
	HX-9100-8001	Dew point sensor, On/Off, Closed for RH > 90 % Hysteresis 1%, 15vDC power
	HX-9100-9001	Dew point sensor, 10 vDC to 0 @90-95%RH, 15vDC power
	HX-9100-9024	Dew point sensor, On-Off, Closed for RH > 90 % Hysteresis 1%, IP44, 1.5m leads, 24vAC
	HX-9100-9324	Dew point sensor, On-Off, Closed for RH > 90 % Hysteresis 1%, IP44, 3m leads, 24vAC
	JCA-EN31	Enthalpy Sensor
Occupancy	JCA-100-048	HVAC Occupy. sensor, ceiling, 3600, 2.4x6.4m, 9-15vDC, Solid State output
	JCA-ISC-BPQ	HVAC Occupy. sensor, wall, 990, 12x12m, 9-15vDC, Solid State output
	JCA-SRA24201S	SSR(slim 20mm), Din Rail w/heat sink, 24vAC, max20A@400C (3kW)
	JCA-G32A-D20	3 phase switch for SSR
	JCA-0015-1B	24vDC power supply, 80-260vAC input